

Audi Pack lift and Neets relay boxes

Regarding products:



Relay boxes: 306-0002, 306-0003, 306-0007, 306-0008

Audi Pack lift and Neets relay boxes

If you have problems with an Audi Pack lift when using Neets relay boxes, please check the lift potentiometer. The potentiometer is set at 2,5 but should be set to 10. Hereinafter the problem should be solved.

Best regards

Neets