


## Removal of spikes when controlling screens

Regarding products:



On some electric screen it have been noticed that the generated spike can destroy the relays inside Neets Control relay box..

To prevent this from happened we have this upgrade package containing 3 protections units. These 3 protections units is placed from live to live (as shown on image bellow).

